

BUILDING SAFETY CERTIFICATE

Sr .No	Particulars	Description
१.	Name Of The Officer	Sub Divisional Engineer P.W.Sub Div No.1 Bhandara.
२.	Name Of The School	St. Marys School , Khat Road Bhandara 441904
३.	Location Of School	Khat Road , Bhandara Tah & Dist Bhandara.
४.	Classification Of Building	Load Bearing/RCC Framed Structure
५.	Plinth Area Floor Wise	
	Wing -A, Gat No — 152/2/2 G + 2	Built Up Area — 1229.00 Square Metre.
	Wing -B , Gat No — 152/1 G + 3	Built Up Area — 2397.00 Square Metre.
६.	Period For Which Certificate is Issued	२०२३-२०२४
७.	Nature of Defects If Any	
	a) Foundation & Basement	R.C.C. Foundations
	b) B)Superstructure	R.C.C. Framed Structure.
	c)Door & Windows	Grill Doors & Windows.
	d)Wood Work	-
	e)Roof	R.C.C. Slab
	f)Flooring	I.P.S. Flooring
	g)Miscellaneous(Crackes..Etc.)	-
८.	Any Major defects noticed which will render the building unsafe in any manner	No Any Major Defects are Noticed.
९.	Whether Maintance Works have been done properly	Yes.
१०.	Whether the structure is Sound or Not for Conducting Classes	Structure Is Sound For Conducting Classes.

Note.:The Stability of the structure is examined also with reference to location,altitude intensity of wind,Exposure of flood etc.

कार्यकारी अभियंता यांचे कार्यालय
सार्वजनिक बांधकाम विभाग, भंडारा

Web Site :- www.mahapwd.com	E-mail:- bhandara.ee@mahapwd.com	दु.क्र . 07184-252412 फॅक्स क्र. 252412
क्रमांक :- साबांविभं/ ९९७ /तां /2023		दिनांक २९ /२/2023

!! CERTIFICATE !!

Certified that the Structure of School Building was Inspected by me On Dt 19./02/2023 and Found to be fit to conduct classes for the Educational year 2023-2024 for the reason stated above.Certificate of Structural Stability From Private Agency Nandurkar Building Consultancy And Certificate of Fire Safety From Office of the Municipal Council Bhandara is Submitted by owner, Necessary Certificate of Electrification fitness Provisions as per Building Code Should be obtained by the owner of the building from Compentent authority.

Place: Bhandara
Date : 20/2/2023

Sub Divisional Engineer
P.W.Sub Division No.1
Bhandara

Executive Engineer
P.W.Division
Bhandara

G:\General Letter.doc

Principal
St. Mary's School,
Bhandara.
CBSE : AFF : No.1130570